Falkirk Council

Gordon Henderson, Asset Management Officer Stephen German, Area Lighting Engineer





Outline

Network Characteristics LED Replacement Project **PN** Benchmarking **Digital Transformation** Room for Improvement Summary Questions



Network Characteristics

Located along the Firth of Forth sharing boundaries with Stirling, North Lanarkshire & West Lothian

992km adopted road length Urban in nature with primary settlements at Falkirk, Grangemouth, Bo'ness, Larbert & Denny

27,045 street lanterns (excluding road signs & bollards) GRC $\sim \pounds 70 \mathrm{m}$










LED Replacement Project



Energy Audit and Strategy Review of street lighting assets

Scottish Government initiative with involvement from Resource Efficient Scotland, Scottish Futures Trust & Zero Waste Scotland

Reduce energy bill Lower carbon footprint Improve level of Service



PN Benchmarking

LEDLA: More than 26,500 streetlights fitted with LED 'white light source' lanterns

ECKWH: Reduced energy consumption from 10,500,000 kw/hrs to 4,500,000 kw/hrs per annum

Saving the Council approximately £900,000 per annum and reducing C02 tonnage from 4215t to 1200t in line with net zero 2030 aims

NOFPB: Improved LED reliability has resulted in reported street light faults dropping by 32%



Digital Transformation

Council of the Future project aimed at modernising and improving Service delivery by embracing new technologies

Lengthy paper-based inspection & instruction process now fully automated via handheld tablets

SLNWR: 97% of customer reported faults now repaired within 2 working days

Digital records for auditing purposes



Digital Transformation





Digital Transformation

Attendance Request Details	×
Item Type:	
Lighting Point	*
Work/Fault Details:	
Street Light Out	* Laute
Unit Number, Road Name & Town	
FSE07 Roebuck Place, ?, Bo'ness	T DT
Control Unit Item Identity Code	d -
11615	
Control Unit Location Description	
Con.Pill - Viewpark Rd at Sub station rear of No.2	- more
Enquiry Comments	
	ma
	Next
	HEAK



Room for Improvement

Unable to select correct lighting column from map. Shown as does not exist	1	6
Unable to select bollard outwith street	3	
Unable to add comments	3	

Month	Ratings	Average rating
January 2023	5	4.8
December 2022	8	4.8
November 2022	8	3.6
October 2022	14	3.5
September 2022	9	2.9

Stakeholder engagement through APSE & SCOTS online roads survey

Data improvement plan to validate asset inventory records in collaboration with internal Web & Digital teams



Summary

LED Replacement Project

Reduced energy bill & lower carbon footprint

PN Benchmarking

Manage performance, improve and innovate

Digital Transformation

Timely & efficient repairs

Room for Improvement

The customer journey



