

APSE Scotland Building & Housing advisory group meeting 20th November 2020

AGENDA

- New CMS Group structure
- COVID-19
- BREXIT
- What's new
- Spotlight on Donibristle Primary School and Clobber Primary School



New CMS Group structure










COVID-19 working safely at CMS































COVID-19 working safely on site







COVID-19 working safely on site







As part of our existing installation process, we identify a "safe room" in each property, which will ensure resident is secure and safe.



COVID-19 challenges

- Supply chain disruption
- Workforce absences due to self isolating / illness
- Implementing COVID-19 safe working practices result in slower speed of works
- Additional PPE costs
- Less usable space in factories / offices due to social distancing
- Mental health & wellbeing of workforce



Challenges - Brexit

We are now focused on the BREXIT deadline of 31st December 2020

- Leading up to the original BREXIT date of 29th March 2019, the following specific actions were agreed and implemented:
 - Stock budgets were increased and additional storage facilities were put in place
 - Key suppliers provided additional volumes.
- We repeated this when BREXIT shifted to 31st October 2019.

We believe the measures above worked, and we are therefore repeating this strategy, COVID-19 permitting, leading up to December 31st 2020.






- Superb energy efficiency
- Patented bubble gasket
- No hard spots
- 8mm overlap inside and out to maintain an excellent weather performance
- Fully tested to the latest enhanced security and weather performance standards

- Reinforcing only required over 1metre
- Energyplus 6 chamber system with U value 0.8 W/m2K
- U value 0.5 W/m2K / noise reduction of 42 decibels achievable
- Unique glazing flipper
- Low threshold




- QR codes on all windows
 - Scan to display information for maintenance staff / emergency repairs






CMS Portal login for live access to contract information





CMS iAuditor for remote site monitoring

 Site Health & Safety audits, pre & post works inspection audits and tenant satisfaction surveys.



Fitting team Have all windows been fitted as per standard fitting instruction (Fixings installed, window fitted plumb and square) Have all cills, facings and ingos been fitted as per standard fitting instructions (sealed, sanded and painted) Are all windows and doors operational (Handles working, no hinge issues, vents operational and sealed properly) Confirmation that no locking handles have been fitted to upper levels Wes Have all internal decoration works been completed to the correct standard N/A Have all external sealant/mastics been completed Have all external sealant/mastics been completed Have all external an internal render/plaster	Question	Response	Details
Fitting team Have all windows been fitted as per standard fitting instruction (Fixings installed, window fitted plumb and square) Have all cills, facings and ingos been fitted as per standard fitting instructions (sealed, sanded and painted) Are all windows and doors operational (Handles working, no hinge issues, vents operational and sealed property) Confirmation that no locking handles have been fitted to upper levels Wes Have all internal decoration works been completed to the correct standard N/A Have all external sealant/mastics been completed Have all external sealant/mastics Ves External works required only.	Date of Installation	18/05/2018, 08:00	
Have all windows been fitted as per standard fitting instruction (Fixings installed, window fitted plumb and square) Have all cills, facings and ingos been fitted as per standard fitting instructions (sealed, sanded and painted) Are all windows and doors operational (Handles working, no hinge issues, vents poperational and sealed property) Confirmation that no locking handles have been fitted to upper levels At we all internal decoration works been completed to the correct standard N/A Have all internal sealant/mastics been completed Have all external sealant/mastics Ves External works required only.	Specification (Type of Window and Doors)	8x White PVC. Tilt and Turn. Trim finish. External trims.	
standard fitting instruction (Fixings installed, window fitted plumb and square) Have all cills, facings and ingos been fitted as per standard fitting instructions (sealed, sanded and painted) Are all windows and doors operational (Handles working, no hinge issues, vents operational and sealed property) Confirmation that no locking handles have been fitted to upper levels Are all it windows and doors to have been completed to the correct standard N/A Have all it external sealant/mastics been completed Have all external an internal render/plaster Have all external an internal render/plaster Line Standard Stan	Fitting team	Kenny Corrigan & Lloyd Reid	
as per standard fitting instructions (sealed, sanded and painted) Are all windows and doors operational (Handles working, no hinge issues, vents operational and sealed properly) Confirmation that no locking handles have been fitted to upper levels Have all internal decoration works been completed to the correct standard N/A Have all wternal sealant/mastics Yes Live all working and sealant/mastics Yes External works required only.	tandard fitting instruction (Fixings	Yes	
operational and sealed properly) Confirmation that no locking handles have been fitted to upper levels Have all internal decoration works been completed to the correct standard N/A Have all external sealant/mastics been completed Have all external an internal render/plaster Have all external an internal render/plaster	as per standard fitting instructions (sealed,	Yes	
been fitted to upper levels Tes Have all internal decoration works been completed to the correct standard N/A Have all external sealant/mastics been completed Have all external an internal render/plaster N/A External works required only.	Handles working, no hinge issues, vents	Yes	
completed to the correct standard Have all external sealant/mastics been completed Have all external an internal render/plaster Mac External works required only.		Yes	
been completed Yes Have all external an internal render/plaster No. External works required only.		N/A	
Have all external an internal render/plaster No External works required only.		Yes	
		No	External works required only.
Appendix 1 Appendix 2 Appendix 3	Appendix 1 Appendix 2 Append	idik 3	
Has the property been left in an acceptable standard post works (clean, hovered, mopped etc etc)	standard post works (clean, hovered,	Yes	
Please take a picture of all windows and doors internally	Please take a picture of all windows and doo	ors internally	



3 consecutive years of zero waste to landfill

- FY2019-20: 2802 tonnes of waste treated
 - 96.5% recycled / remade into new products
 - 3.1% reused
 - 0.4% used by waste-to-energy specialists.





- FD60 fire door
 - Dual sided
 - Fully certified 60 minute fire door
 - Tested on both sides

- FD30 composite fire doors
- In-house CAD designer
 - CAD drawings produced in-house for projects







Spotlight on Fife Council

Window framework with CMS covering domestic dwellings and public buildings

Example: Donibristle Primary School, Dalgety Bay

- COVID-19: single glazed aluminium windows, not providing enough ventilation
- New windows required urgently: 10-week project from start to finish
- New PVC double glazed top hung casements over 500mm fixed lights



"I just wanted to say a massive thank you for the hard work that went into the window replacement work at Donibristle. We have been absolutely delighted today - adults and children alike!

Many thanks Karen Hart Acting Headteacher, Donibristle Primary"



Spotlight on East Dunbartonshire Council

 Window framework with CMS covering domestic dwellings and public buildings

- eg Clobber Primary School
 - Vandalised and set on fire during COVID-19 shutdown
 - Need for CMS to remobilise quickly to ensure school ready for reopening





Thank you

Any questions?

