

APSE

Electrical Installation Condition Reports (EICR)

Colin McInnes, 22nd February 2024

Contents



- Legislation
- EICR Requirements
- Current Challenges
- Remedial Works
- Process Benchmarking in Scotland

Are you concerned?



"For every year from 2015 to 2020, electricity was five times more likely than gas to be the cause of a fire in domestic dwellings"

Legislation:



- More Legislation relating to Gas than Electrical Installations!
- Variations between Scotland, England & Wales
- Different for Private Rented Sector to Social Rented Sector
- Regulatory requirements fall across a range of legislation e.g.

Legislation: Scotland



"Although **not a legal requirement**, it is best practice for council housing providers to complete an Electrical Installation Condition Report (EICRs) within your home every five years."

Mandatory that properties are electrically safe! (SHQS Amendment 2020)

EICR Requirements



- Ensure national standards for electrical safety are met.
 (18th Edition of wiring regulations).
- Properties are inspected and tested by a qualified and competent person at an interval of at least every 5 years.
- Obtain a report which gives the results and sets a date for the next inspection and test.
- Supply a copy of this report to the existing tenant within 28 days of the inspection and test.
- Supply a copy of this report to a new tenant before they occupy the premises.
- Remedial or further investigative work is completed within 28 days or any shorter period if specified as necessary in the report.

Current Challenges



- EICR Registers
- Compliance Rates / Regulator checks
- Limited Resources Market Shortages
- Access Restrictions
- Completion of Remedial Works
- Checks & Balances

EICR Registers



- Accuracy of data
- Digital solutions
- Forward programme planning
- Compliance Rates
- No Access rates
- Remedial works

Compliance Rates



- What is your Current position?
- How do you handle HMO Properties?
- How do you handle Void properties?
- If not 100% what are you currently doing to achieve this?
- Regulator comments / input?

Resourcing



- Limited Availability of qualified electricians
- Market Shortages
- Current demand
- Sub-contractor availability
- Cost to deliver service

Access Restrictions



- 100% access rate Yes / No?
- "No Access" Protocols / Procedures.
- Legal process used by authorities.
- Forced entries?
- Recovery of costs Tenant recharge?

Remedial Works



How do you deal with Remedial works identified in EICR?

Classifications:

- Code 1 (C1): Danger present. Risk of injury.
- Code 2 (C2): Potentially dangerous.
- Further Investigation (FI): Further investigation required without delay.
- Code 3 (C3): Improvement recommended.

Remedial Works



Code C1 & C2

Hazards should be completed immediately following the inspection. Same visit?

Code C3 and FI

Hazards should be completed within 28 days following inspection.

Process Benchmarking



- EICR issues raised at Advisory Group Meeting.
- Scottish Authorities Working Group establish 2023.
- EICR Survey undertaken December 2023.
- Analysis of results undertaken February 2024.
- Next Steps.

EICR Survey Highlights



- Average cost to undertake EICR is £160.00.
- 100% carry out P1 repairs during inspection.
- 86% carry out P2 repairs during inspection.
- 71% of authorities check smoke alarms during inspection process.
- 100% carry out forced entries.
- Tenancy Agreements being used by authorities as means to force entry to property.

Next Steps



- Discuss findings of EICR Survey.
- Agree on key priorities to focus on.
- Develop on areas of good practice/processes.



Questions?

LOCAL SERVICES LOCAL SOLUTIONS



Contact details

www.apse.org.uk

Association for Public Service Excellence

2nd floor Washbrook House, Lancastrian Office Centre, Talbot Road, Old Trafford, Manchester M32 0FP.

telephone: 0161 772 1810

fax: 0161 772 1811 web:www.apse.org.uk





GB 11409





GB 11132



GB 14074