



APSE highways networks

Pothole App

9 September 2026

Background:

Quality assurance rather than condition / safety survey

Lived experience of citizens and meaningful information for elected members

- Lasting quality of pothole repairs
- Number of potholes per mile/km/street inspected
- Inspection of all elements of Council front line services which affect quality, aesthetics and usability of streets to citizens in one visit


Other aspects of public realm collected through LAMS



Inspection Apps



bit.ly/APSECLAMS



bit.ly/APSELAM



bit.ly/40Cjptr




bit.ly/3ZIOJM



LAMS is....

- Land Audit Management System.
- Introduced 2015 – digitised 2018.
- Monitor grounds maintenance, also be applied to street cleansing for a total street scene quality score.
- Can be used for cemetery/crematoria grounds.
- Simple and effective performance measuring system.
- ‘what the public would see’ rather than requiring a technical inspection.
- May be used by volunteers.
- Around 50 member L/A’s using the system (including several Core Cities)




What does it monitor?

	Grounds Maintenance	Street Cleansing	Cemetery Land Maintenance
Grass cutting	✓		✓
Shrub bed maintenance	✓		✓
Flower bed maintenance	✓		✓
Overall grounds maintenance	✓		✓
Number of flowers occurring naturally in a 1 sqm area	✓		✓
Pollinators within shrub bed	✓		
Pollinators within meadow	✓		
Surface weeds	✓	✓	✓
Detritus	✓	✓	✓
Litter	✓	✓	✓
Fly tipping	✓	✓	✓
Fly posting	✓	✓	
Dog fouling	✓	✓	✓
Bins overflowing	✓	✓	✓
Bin structure	✓	✓	✓
Bin cleanliness	✓	✓	✓
Graffiti	✓	✓	
Vandalism	✓		✓
Staining / gum		✓	

Two parts to the process for all our systems

Part 1 - Inspections – using the App - out in the field.



10:45


apse
surveys

Email

Password

LOGIN

FORGOTTEN PASSWORD



10:28

apse surveys

Available until
01/04/2026

Download

Questionnaire
Training Grounds and Streets
Survey 2025/26

Available until
01/04/2026

Start


Questionnaire
Training Grounds Survey
2025/26

Available until
01/04/2026

Start

Questionnaire
Training Streets LEAMS Survey

Questionnaires In Progress



10:27

< Back

frequency (standard
maintenance)
Zone 3 – Low frequency (low
maintenance)

General Information

Amend address if required
Ward: Hemsworth Ward

3B Tun Lane, Barnsley, S72 9...

Area
North

Zone
1

Site type
Public open space

Continue

Two parts to the process for all our systems

Part 1 - Inspections – using the App - out in the field.

10:20

< Back

Pollinator grade (within meadow)

A - Excellent standard ×

Are there any hard surfaces/paths within your inspection area?

Yes ☒

No ☐

Hard surface weeds grade ⓘ

C - Significant weed growth ×

Detritus grading ⓘ

A - No detritus present ×

Litter grade ⓘ

A - Excellent standard ×

Was today a refuse collection day?

Yes ☐

Fly tipping grade



10:22

< Back

Comments - 2025/26

Comments

Add further background information if required

Send Later Send Now

Two Parts to the Process

Part 2. Approvals – reviewing and exporting the data – using the dashboard at your workspace.

surveys

Surveys ▾

Organisation ▾

Hello Helen Taylor

Logout

Survey data for approval

Review your answer sets for your surveys below. Expand each answer set to view answers and take appropriate action

+/- Show or hide answer set

+/- Show or hide answer set

Actions	Location	Select a ward -	Zone	Land Type	Grounds Maintenance Grading	Hard surface weeds grading	Litter Grading	Detritus Grading	Fly Tipping Grade	Dog Fouling Grade	Bins Overflowing	Bin itructural Grade	Bin Cleanliness Grade	Graffiti Grade	Staining Grade	Ground Condition Grade	Wat Grad
☒ Approve ☐ Not approved	3B Tun Lane, Barnsley, S72 9BZ	Abram Ward	1	MR	C	C	A	A	A	A	N/A	-	-	A	C	-	-

+/- Show or hide answer set


+/- Show or hide answer set

<


>

© 2018 - Bbits Survey v1.0.17

USING THE APSE RANDOMISER IN THE APP



On opening the app, login with the email and password you normally do.




If you have been assigned any randomiser sets of locations they will show above your Questionnaires.

Click the Download opens the map displaying all your locations – it also starts the timer for 48 hours to complete the list.



A randomiser list opens the map with all the locations in the list plotted.

Select a pin, the nearest to your location (shown as a blue dot). And you get a Navigate and Start button.



Navigate – takes you out to your native mapping application and directions.

Start – starts and opens (as if from the front screen) the relevant survey for the location you selected to complete the inspection.

Road Hierarchy	Principle, Secondary, Link, Local, Classified, Un-Classified
Carriageway Grade	Grade
Fully Refurbished / Recently Replaced	Y/N
Dominant Construction Type	Asphalt, Block/Setts, Concrete
PH >40mm Cat 1's	Count
PH <40mm - 20mm Cat 2's	Count
PH >10mm <20mm Cat 3's	Count
% Patching	0%, 25%, 50%, 75%, 100%
% Minor Fretting	0%, 25%, 50%, 75%, 100%
% Major Fretting	0%, 25%, 50%, 75%, 100%
% Minor Deterioration	0%, 25%, 50%, 75%, 100%
% Major Deterioration	0%, 25%, 50%, 75%, 100%
Ridge or Hump > 40mm	Count
Depression / Rutting	Y/N
Standing Water	Count / N/A
Kerb Defect	Count / N/A
Kerb Missing	Count / N/A
Marked up Defects	Count
3rd Party Iron works Raised	Count / N/A
3rd Party Iron works Low	Count / N/A
Rocking 3rd Party Iron Works	Count / N/A
Cracks Around 3rd Party Iron works	Count / N/A

Footway Grade	Grade
Fully Refurbished / Recently Replaced	Y/N
Prestlge	Y/N
Dominant Construction Type	6mm, Micro Asphalt, Flags, Blocks, Concrete
Secondary Construction Type	6mm, Micro Asphalt, Flags, Blocks, Concrete
Trip >20mm	Count
Trips <20mm	Count
Flag/Block Gap >15mm	Count / N/A
Rocking Slab	Count / N/A
% Patching	0%, 25%, 50%, 75%, 100%
% Minor Fretting	0%, 25%, 50%, 75%, 100%
% Major Fretting	0%, 25%, 50%, 75%, 100%
% Minor Deterioration	0%, 25%, 50%, 75%, 100%
% Major Deterioration	0%, 25%, 50%, 75%, 100%
Standing Water	Count / N/A
Damaged Edging	Count / N/A
Missing Edging	Count / N/A
Marked up Defects	Count
Raised Iron Works	Count
Low Iron Works	Count
Rocking Iron Works	Count
Cracks Around Iron Works	Count



Street Lights Number	Count
Fully Refurbished / Recently Replaced	Y/N
ADB	Count
Hanging Lantern	Count
Leaning	Count
Door Off	Count
Street Signs Number	Count
Fully Refurbished / Recently Replaced	Y/N
Number OGV	Count
Sign Face Damage	Count
Sign Face Cleanliness	Grade
Post Damage	Count
Sign Face Graf/FP	Grade
Illuminated Signs Number	Count
Fully Refurbished / Recently Replaced	Y/N
Illuminated Signs ADB	Count
Damaged Lamp	Count
Missing Lamp	Count
Boxes Number	Count
Fully Refurbished / Recently Replaced	Y/N
Door Issues	Count
Boxes Graffiti / FP	Grade

Contact details

Debbie Johns,

Director – APSE performance networks

Email: djohns@apse.org.uk



INVESTORS IN PEOPLE®
We invest in people Gold

www.apse.org.uk

Association for Public Service Excellence
3rd floor, Trafford House, Chester Road,
Old Trafford, Manchester M32 0RS.
0161 772 1810
www.apse.org.uk